

Pump Evaluation

Date: 12/22/18

Unit#: 1788

Location: OKC

Pump Make: Schwing

Size: 47MSX

Pumpkit: 2525H-6

Boom: 4-sec

Pump Model: 2525H-6/5475X

Pump SN: 170526191

Year: 2005

Truck Make: Mack

Truck Model: M1688S

Truck VIN: 1M2K197C95M026745

Year: 2005

Engine Make: Mack

Engine Model: A1400A set

Trans Make: Mack

Trans Model: T309L

Truck Hours: 22610

Truck Miles: 760650

Pump Hours: 17300

(Percentage and/or Explanation)

Truck condition:

Tires: 75%

Suspension: 65%

Brakes: 60%

Exhaust: 70%

Engine: 65%

Transmission: 75%

Transfer Case: 75%

Valve Adj:

DOT: Due 6-19

Leaks: some

Paint: 50%

Cleanliness: 50%

Pump Condition:

Wear Parts: 50%

Barrels: 70%

Diff Cyls: 60%

Pump Pressures: 90%

Pipe: 35,000 yds

Hyd Cyls: 70%

Handvalves: Minor leaks

Hyd Oil: 80%

Agitator: 40%

Hopper: 60%

Accumulator: 65%

Boom Inspection: Done on 5/18

Remote Boxes: 65%

Auto Greasers: Manual on frame and hopper. Auto on boom

Overall Operation:

Good Pump

Recent Major Repairs:

Truck:

Lt Ft Vert Cyl 9-18 New Turbo 10-18 Shift Tower Reman 11-18
A/c Dryer 11-18 Wiring Harness Engine 11-17 Reman Trans 5-16
Exhaust Manifold 11-15

Pump:

R/V Reman W-Plate and Inserts 4-17 New Barrels 10-15
Stable Box New Fork + Gear 12-17

Misc:







