

Pump Evaluation

Date: 4/13/18 Unit#: 2820
Location: Tyler Boom: 4 section
Pump Make: Putz Pumpkit: A4125HD (32-AUG) Year: 1998
Pump Model: BSF36.16H Pump SN: 21980600453 Year: 1998
Truck Model: Mack Truck VIN: 1M2K189C0WMD10803 Trans Model: T2090
Engine Make: E7 Trans Make: Mack Pump Hours: 1997
Truck Hours: 2102 Truck Miles: 216320

(Percentage and/or Explanation)

Truck condition: 85%
Tires: 90%
Brakes: 75%
Engine: 100%
Transfer Case: 75%
DOT: 11-2017
Paint: 90%

Suspension: 100%
Exhaust: 90%
Transmission: 100%
Valve Adj: New Engine
Leaks: None
Cleanliness: 80%

Pump Condition: 90%
Wear Parts: 90%
Diff Cyls: 100%
Pipe: 60%
Handvalves: 70%
Agitator: 80%
Accumulator: 100%
Remote Boxes: 85%

Barrels: 100%
Pump Pressures: 360
Hyd Cyls: 90%
Hyd Oil: 80%
Hopper: 80%
Boom Inspection: August 2018
Auto Greasers: 100%

2820

Overall Operation:

good smooth boom and pump

Recent Major Repairs:

Truck:

New inframe engine Rebuild new turbo

Pump:

New Hyd Pumps on main Various hyd lines Replaced
Whole truck has been Repainted new fvent lines

Misc:

New swing 90° and Transition 90° + Reducer

needs new hopper rubber